

OUT5523i

4036

1965 MAR 12 21 19Z

25X1

COMMO AUTO

1. CONFIRMING CONVERSATIONS BETWEEN

25X1

REQUESTS ALL TRANSMISSIONS OVER THE 1004 DATA LINK FOLLOW

25X1

A DEFINITE PROCEDURE AS OUTLINED BELOW:

A. ALL TRANSMISSIONS TO BE TERMINATED BY AN END SENTINEL

BLOCK. IT WOULD BE MOST DESIRABLE IF THE END SENTINEL BLOCK INCLUDED

A BLOCK COUNT OF THE DATA TRANSMITTED.

B. IF TWO DISTINCT FILES OF DATA SHOULD BE SENT THERE SHOULD

BE A POSITIVE INDICATION SEPARATING THE TWO FILES. THIS POSITIVE

INDICATION SHOULD BE AN END SENTINEL BLOCK.

2. THIS PROCEDURE IS NECESSARY TO INSURE POSITIVE ASSURANCE

15 MAR 1965

THAT ALL THE DATA HAS BEEN RECEIVED. THE DATA RECEIVED IS OFTEN

FURTHER PROCESSED BY COMPUTER PROGRAM AND WITHOUT A POSITIVE

INDICATION GARBLED AND ERRONEOUS DATA CAN BE PROPAGATED.

3. FOR THE ABOVE REASONS IT IS RECOMMENDED THAT A STANDARD

OPERATING PROCEDURE FOR DATA TRANSMISSIONS BE INSTITUTED BY THE

ADDRESSEE.

~~TOP SECRET~~

/END OF MESSAGE/

COPIES RECEIVED			7
CyNo.	Office	Act.	
1	Master File		
2	OS		
	ADMIN		
	SEC BR		
	P&DS		
	CSD		
3,4	IRD		
	FD		
	IRB		
	T-D		
	P&D		
	CIA/		
	DIAX-4		
	SPAD		
	NSA/L		
	DIAAP		
5	Cammo		
	Destr		

GROUP 1
Excluded from automatic
downgrading and
declassification

TOP SECRET